


Parts needed to mount the REGULOR extrusion



Tools needed for mounting:

- double-sided tape

NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure. More mounting procedures and related accessories can be found at www.klusdesign.eu



